


**SHERLINE  
PRODUCTS**  
INCORPORATED 1974

## Lubrication

- **MACHINE SLIDES**—Use a light oil such as sewing machine oil on all points where there is sliding contact. This should be done immediately after each cleanup. (We grease the slides at the factory to ensure the lubrication stays in place during shipping, but light oil will work fine once you begin using the machine.)
- **LEAD SCREW, TAILSTOCK FEED SCREW, CROSSLIDE SCREW**—Sewing machine oil should be placed along all threads regularly. At the same time, check that the threads are free from any metal chips. Use an air hose or paint brush to keep them clean. All Sherline mills now include oil reservoirs on the X/Y axes and the Z axis to help keep critical parts lubricated. Another new feature is the brass leadscrew cover that keeps chips off the rear of the Y-axis leadscrew.
- **TAILSTOCK SPINDLE**—Wind out the spindle as far as it will go and lightly oil it with sewing machine oil.
- **HANDWHEEL**—A few drops of light oil behind the handwheel will reduce friction between the surfaces and make operation easier and smoother.
- **HEADSTOCK BEARINGS**—These bearings are lubricated at the factory for the lifetime of the machine and should not need further lubrication. **DO NOT** break the seals.
- **MOTOR**—Sealed ball bearings require no maintenance.

### Special notes for CNC machines



*Oil passages are shown in blue. The mill oiler is located in the front right corner of CNC mill saddles.*

Use of stepper motors and computer control can introduce a lot more turns on a leadscrew in a given amount of time compared to turning it by hand. Since the machines were developed before the advent of CNC, you should be aware that CNC demands lubrication more often than when used manually. Machine slides, and the Z-axis column in particular should be lubricated with light machine oil about every two hours during CNC use. To help keep the X and Y slides on the mill lubricated, we have introduced a mill oiler as standard equipment on new CNC machines. (It is optional on manual machines.) This small reservoir holds oil that is distributed to the X and Y leadscrews. The oiler is located in the right front corner of the mill saddle. Unscrew the cap and fill the reservoir before each CNC session and refill if necessary after several hours of use. Oil may continue to leak out after use, but the reservoir does not hold an extremely large volume of oil, so cleanup should not be a problem. Even so, we suggest that CNC machines should be set in a metal pan like the kind used under auto engines on a garage floor. This will help contain chips, coolant and excess lubrication, making cleanup easier. They are available from any auto parts store.

### When NOT to lubricate certain surfaces

The mating surfaces of the arm, the column and the column cap on the Model 2000 mill are to be kept free from lubrication. Tightening the column bolt causes friction between these surfaces to resist movement of the arm during the forces and vibration of machining. If these smooth surfaces are lubricated, the arm or the column could move during machining even if the bolt is securely tightened. Clean these surfaces periodically with mild detergent or bathroom spray cleaner to keep a good “bite” between surfaces. The same goes for the surfaces between the “knuckle” and the ends of the swing arm. These surfaces are smooth enough that adjustment is easily accomplished with the nut loosened even without lubrication. They should be free of dirt and chips, but please resist your natural inclination to lubricate them, as they do their intended job better when dry.

Thank you,  
Sherline Products Inc.