

#### PRODUCT DESCRIPTION

- 6600—CNC Chucker w/3C headstock, ball screws, high-torque stepper motors & PC w/4-axis driver & software
- 6610—CNC Chucker w/3C headstock, ball screws & 2 high-torque stepper motors
- 6620—CNC Chucker w/3C headstock, ball screws, 2 high-torque stepper motors & 4-axis driver box (no PC)

## CNC Chucker Lathe

P/N 6600, 6610, and 6620

### User Instructions for CNC Chucker Lathe with Ball Screws

#### Notes:

1. Do not get any chips on your ball leadscrew. If chips get into the ball nut, they will ruin the ball nut. On the headstock side of the table, the ball screw is protected with a brass tube. This makes it virtually impossible for chips to get onto the ball screw. On the backside of the table, the ball screw is protected by the accordion way cover. If this way cover gets filled with chips, it will become a “chip compactor” and two things will happen. One is that you will start to lose table travel in the Z-axis, because the chips are making the “closed cover thickness” of the cover thicker. Secondly, you will tear the cover and expose the ball screw to chips.
2. Do not blow the chips off your machine, use a small brush and brush them off. Blowing chips increases the chances of getting chips on your ball screw.

#### Machine Accuracy

Your machine has been checked at the factory for alignment and backlash.

#### Alignment

We indicate in the 3/8" hole on the gang tool post with a .0001" test indicator. We shim the headstock as needed to get the spindle centerline within .001" of the tool post.

#### Backlash

We check the mechanical backlash on the X and Z-axis with a .00005" test indicator. The mechanical backlash on both axis is less than .001".

#### Operating and Set-up Tips

1. Lubricate your machine with a light oil such as 3-in-1 oil. For the Z-axis, fill the oiler cup once a day (see Figure 1). This is a gravity feed system and the oil will flow down the sides of the base after a while. Mounting your machine inside a shallow basin (such as a cookie sheet) is recommended. For the X-axis, put a few drops of oil on your finger and wipe it onto the exposed dovetail surfaces underneath the table (see Figure 2).

Then jog the table back and forth to spread the oil on both the X and Z-axis before running the machine.




FIGURE 1—Z-axis oiler cup




FIGURE 2—The arrows indicate the surfaces underneath the table where oil should be applied.

2. Gang tool post: Your gang tool post will come from the factory mounted on the rear T-slot. This will give you more travel for the tools in the Z-axis. It will also offset the amount of usable space that is taken up by chucks and other holders that are mounted in the tool post. We center the gang tool post so you can add holders on either side of it if desired. Indicate the face of the gang tool post so it is perpendicular to the centerline of the spindle.
3. If you mount our rear cutoff tool post (P/N 3018) on the stepper motor side of the table (see Figure 3), you can use the cutoff holder as a programmable stop for your material. You can finish your program with a part-off cycle. Then you are already in position to start your next part.




FIGURE 3

4. If you are going to be using the gang tooling tool post for most of your parts, it decrease your set up time if you indicate in each of the 3/8" holes. Move your machine until it hits the hard stops. Then move one full revolution (2.0mm) away from the hard stop. Zero out your X-axis. Place a test indicator in a collet in the headstock. Then use the jog mode and jog the first hole over to the spindle centerline. Using the Jog Increment function move the X and Z-axis until the hole is indicated in. Write down the X-axis position for the first hole. NOTE: Make sure to write "Rad" or "Dia" for your X-axis position depending on how you are going to program your parts. The control page shows both values (see Figure 4).




FIGURE 4

5. The more tools that you are using for your part, the longer and more complex the program becomes. In general, you cannot restart in the middle of the program. This means that if you have already dialed in the first four tools and you are working on the fifth tool, you can't just restart the program on the fifth tool. You have to run through the entire program again until it gets to the fifth tool. This is very tedious and time consuming. A better way is to write several short programs, one for each tool using the same home position and each tools individual tool offset values from the tooling page.

Now run each individual short tool specific program for each tool. Once you have run all of the tool specific programs and dialed in each tool, you can do one of the following choices.

- a. Merge all of the small tool specific programs into one large continuous program.
- b. Turn each of the tool specific programs into "Sub Programs." Then make a "Main / Master" program that calls up each of the sub programs in sequence.

#### The Lathe Uses a GUI Control Page and Tooling Page

1. Start up procedure:
  - a. Click on the icon that represents your machine (Lathe Inch or Lathe Metric).
  - b. Home out your machine.
2. If you already have a home position, turn your X and Z handwheels to the correct handwheel setting. Make sure the stepper motor power switch on the side of the PC is in the "OFF" position.
3. If you don't already have a home position, then you are just going to zero your machine at its current location. Zero your axis.
4. Click on the "Toggle Emergency Stop" icon (See Figure 5).




FIGURE 5



- Click on the “Toggle Machine Power” icon.




FIGURE 6

- Click on the axis that you wish to Zero out. The dot will turn black when that axis is activated. Now click on the “Home Axis” icon.




FIGURE 7—Red arrow is pointing to the X-axis radial button.

- Choose the next axis, and then home it too.




FIGURE 8—Click the Z-axis radial button.

- Now your position page will show Zero for your radius, diameter, and Z-axis.

### To Access the Tooling Page

- Click on “File” and then click on “Edit Tool Table.”




FIGURE 9—Please note the red arrows indicating the “File” and “Edit tool table...” menus.

- This is what your tooling page will look like:

- The “Tool” and “Pocket” should be the same tool number.
- Your “X” is the distance from your X Home Position, to the “Centerline” of the part. You will acquire this number by making a cut on the OD of the stock, Writing down the X position shown on the position screen, Measure the diameter of the turned surface, and then adding the radius of that diameter to the X value that is shown on the position page. The sum of those two values is what you enter for your X value on the tool table. See example below.




FIGURE 10—Here is a link to more information on LinuxCNC Tool Tables (<http://wiki.linuxcnc.org/cgi-bin/wiki.pl?ToolTable>)



For this example, we are using a 1/4" dowel pin and just touching off on the side of it.



FIGURE 11—Notice the carbide tip on the left just touching the side of the dowel

Write down the X Radius value from the position screen (X-5.6438)




FIGURE 12

Measure the diameter of the part (.2502)



FIGURE 13

Add the radius of the part to the radius amount from the position page and enter that in the X value on the tool page ( $-5.6438 + -.1251 = -5.7689$ )

c. To get your Z-axis offset numbers:

Take the longest tool, touch it off on the front of the stock, then move in the Z+ direction by the amount of clearance that you want (Ex 1.00"). Now Zero out the Z-axis (this position will now be your Z Home Position).

The Z offset for the longest tool would then be Z-1.00".

Now touch off the rest of the tools and write down their Z position from the position page.




FIGURE 14—Notice the carbide tip on the left just touching the front of the dowel




FIGURE 15

#### Front and Back Angle for Your Insert or other Cutting Tool

Below is a diagram showing how the front and back angles are defined. The insert shown is a 55-degree insert, which is 5 degree off square. The back angle is 30 degrees. The front angle is the sum of the back angle and the included angle of the insert ( $30 + 55 = 85$ ).




FIGURE 16—The tool above is defined below on the tool page as tool #4 (fourth down from the top of the list in Figure 17).

The tool #4 illustrated in Figure 16 above is a LH tool which is why the front and back numbers are negative in Figure 17 below.

V	W	DIAM	FRONT	BACK	ORIEN	COMMENT
		0.04	90.0000C	90.0000C	8	.040 cut off
		0.08	90.0000C	90.0000C	9	#3 ccenter drill
		0.094	90.0000C	90.0000C	9	3/32" .094 drill
		0.015	-85.0000C	-30.0000C	2	55 diamond l.h.
		0.015	85.0000C	30.0000C	3	55 diamond r.h.
		0.03	90.0000C	90.0000C	6	.030 groove tool

FIGURE 17

Any time that you make a change to the tool page, click on "Reload Table" and "Save File."

#### Lathe Program

1. This program was set up for a part on our CNC Chucker Lathe, which has gang tooling (see picture below).




FIGURE 19

2. For this part we are using the following tools:
  - a. .040 Cut Off Tool (which is also used as a stop to set the stock distance from the front of the collet)
  - b. #3 Center Drill
  - c. 3/32" .094" Jobber Drill
  - d. L.H. 55 degree insert tool
  - e. R.H. 55 degree insert tool
  - f. .030 wide groove tool






FIGURE 19—Note: the LH and RH 55 degree tools are set up to cut on opposite sides of the part.

3. Here is a print of the air fitting that we are making.




FIGURE 20

4. Here is a copy of the program.

```
%
(Machine Setup - 1 .040 wide Cutoff )
(TOOL #1 )
G80 G94 G7 G40 G20 G18 G90 G54
T1 M6 G43
G00 X-.6 Z.1
G00 Z-.820
G00 X-.208
G01 X-.118 F2.
G00 X-.208
G00 Z-.800
G01 X-.128 Z-.820 F1.0
```

---

G01 X.020 F3.0  
G00 X0.0  
G00 Z.100  
G00 X0.0  
M01  
G01 Z0.0  
M01  
G00 Z1.  
G49  
G90G00G54 X0 Z0  
(TOOL #2 2 CENTER DRILL )  
N200 G00 G94 G7 G40 G20 G18 G90 G54  
T2 M6 G43  
G90 G00 Z.1  
G00 X0  
G01 Z-.100 F4.0  
G90 G00 Z1.2  
G49

(TOOL #3 0.0940 Dia.118.0000 Deg. 1.0000 CL )  
N300 G00 G94 G7 G40 G20 G18 G90 G54  
T3 M6 G43  
G00 Z.1  
G00 X0.0  
G01 Z-.088 F2.0  
G00 Z.1  
G00 Z.060  
G01 Z-.37  
G00 Z.1  
G00 Z-.350  
G01 Z-.464  
G00 Z.1  
G00 Z-.440  
G01 Z-.558  
G00 Z.1  
G00 Z-.530  
G01 Z-.580  
G00 Z.1  
G00 Z-.560  
G01 Z-.630  
G00 Z.1

---

G00 Z-.610  
G01 Z-.680  
G00 Z.1  
G00 Z-.660  
G01 Z-.730  
G00 Z.1  
G00 Z-.710  
G01 Z-.785  
G00 Z.1  
G00 Z-.76  
G01 Z-.840  
G00 Z.2  
G49  
(TOOL #4 55 DIAMNOD BACKSIDE )  
N400 G80 G94 G7 G40 G20 G18 G90 G54  
T4 M6 G43  
G00 X-.7  
G00 Z0  
G01 X0.0 F3.0  
  
G00 X-.7 Z.052  
G00 X-.57  
G01 X-.47 Z.002 F6.  
G01 Z-.8639  
G02 X-.5095 Z-.884 I.0232 K-.0426  
G02 X-.5197 Z-.9024 I.0533 K-.0247  
G01 X-.52 Z-1.  
G01 X-.62 Z-.95  
G00 Z.052  
G00 X-.52  
G01 X-.42 Z.002  
G01 Z-.8579  
G02 X-.47 Z-.8639 I-.0005 K-.0532  
G01 X-.57 Z-.8139  
G00 Z.052  
G00 X-.47  
G01 X-.37 Z.002  
G01 Z-.8578  
G01 X-.42  
G01 X-.52 Z-.8079  
G00 Z.052  
G00 X-.42  
G01 X-.32 Z.002



---

G01 Z-.8578  
G01 X-.37  
G01 X-.47 Z-.8078  
G00 Z.052  
G00 X-.37  
G01 X-.27 Z.002  
G01 Z-.4807  
G02 X-.3044 Z-.498 I.0124 K-.0296  
G02 X-.3098 Z-.5083 I.0351 K-.0146  
G01 X-.31 Z-.5744  
G01 Z-.8578  
G01 X-.32  
G01 X-.42 Z-.8078  
G00 Z.052  
G00 X-.32  
G01 X-.22 Z.002  
G01 Z-.2335  
G02 X-.23 Z-.2474 I.0165 K-.0138  
G01 Z-.4778  
G02 X-.27 Z-.4807 I-.0033 K-.0475  
G01 X-.37 Z-.4307  
G00 Z.052  
G00 X-.27  
G01 X-.17 Z.002  
G01 Z-.0214  
G02 X-.1823 Z-.0313 I.0136 K-.0153  
G02 X-.184 Z-.0494 I.0705 K-.0122  
G01 Z-.2097  
G01 X-.22 Z-.2335  
G01 X-.32 Z-.1835  
G00 Z.052  
G00 X-.22  
G01 X-.12 Z.002  
G01 Z.0006  
G01 X-.1298 Z-.0017  
G01 X-.1687 Z-.0207  
G01 X-.17 Z-.0214  
G01 X-.27 Z.0286  
G00 Z.052  
G00 X-.1867  
G01 X-.0867 Z.002  
G01 X-.1122 Z.0017  
G01 X-.12 Z.0006

---

G01 X-.22 Z.0506  
G00 X-.53  
G00 Z-.2356  
G01 X-.33  
G01 X-.23 Z-.2856  
G01 X-.2282 Z-.3002  
G01 X-.1984 Z-.3275  
G01 X-.184 Z-.3404  
G01 Z-.3571  
G01 Z-.4777  
G01 X-.23 Z-.4778  
G01 X-.33 Z-.4278  
G00 X-.61  
G00 Z-.5244  
G01 X-.41  
G01 X-.31 Z-.5744  
G02 X-.3019 Z-.5959 I.0383 K-.004  
G01 X-.26 Z-.6326  
G01 Z-.8578  
G01 X-.31  
G01 X-.41 Z-.8078  
G00 Z-.5826  
G00 X-.36  
G01 X-.26 Z-.6326  
G01 X-.21 Z-.6759  
G01 Z-.8577  
G01 X-.26  
G01 X-.36 Z-.8078  
G00 Z-.6259  
G00 X-.31  
G01 X-.21 Z-.6759  
G01 X-.194 Z-.6899  
G03 X-.188 Z-.7022 I-.0114 K-.0093  
G01 Z-.8577  
G01 X-.21  
G01 X-.31 Z-.8077  
G00 X-.6  
G00 Z.2  
G49

(TOOL #5 55 DIAMOND FRONTSIDE )  
N500 G80 G94 G7 G40 G20 G18 G90 G54  
T5 M6 G43

---

G00 X.7 Z.0497  
G00 X.1038  
G01 X.0038 Z-.0003 F4.  
G01 X.0942  
G03 X.1131 Z-.0041 I-.0006 K-.0153  
G01 X.1503 Z-.0223  
G03 X.164 Z-.0395 I-.0127 K-.015  
G01 Z-.2103  
G01 X.2071 Z-.2391  
G01 X.21 Z-.2464  
G01 X.2092 Z-.2977  
G01 X.2023 Z-.3063  
G01 X.1659 Z-.3378  
G01 X.164 Z-.3419  
G01 Z-.4797  
G01 X.2308 Z-.4799  
G01 X.2424 Z-.481  
G03 X.2664 Z-.4869 I-.0074 K-.03  
G03 X.2892 Z-.5077 I-.0177 K-.0232  
G03 X.2884 Z-.5865 I-1.3457 K-.0332  
G03 X.2761 Z-.6006 I-.0428 K.0102  
G01 X.1744 Z-.6887  
G02 X.168 Z-.6965 I.0063 K-.0071  
G01 Z-.8597  
G01 X.4104 Z-.8599  
G03 X.4786 Z-.8766 I-.0016 K-.0463  
G03 X.4973 Z-.8955 I-.0308 K-.027  
G03 X.5 Z-.9172 I-.0777 K-.0157  
G01 Z-1.  
G01 X.6 Z-.95  
G00 X.8  
G00 Z.5  
G00 G49  
(TOOL #6 OD GROOVE .030 WIDE )  
N600 G80 G94 G7 G40 G20 G18 G90 G54  
T6 M6 G43  
G00 X.5  
G00 Z-.3149  
G00 X.274  
G01 X.214 F4.  
G00 X.254  
G00 X.224  
G01 X.184



---

G00 X.274  
G00 Z-.3349  
G01 X.214  
G00 X.254  
G00 X.224  
G01 X.184  
G01 X.204 Z-.3299  
G00 X.274  
G00 Z-.3447  
G01 X.214  
G00 X.254  
G00 X.224  
G01 X.184  
G01 X.204 Z-.3397  
G00 X.274  
G00 Z-.3453  
G01 X.23  
G01 X.25 Z-.3403  
G00 X.254  
G00 X.184  
G00 X.2348  
(Machine Setup - 1 Turn Groove Finish )  
(TOOL #6 OD GROOVE .030 WIDE )  
G00 X.5 Z-.3703  
G00 X.25  
G01 X.21 Z-.3503 F4.  
G01 X.164 Z-.3497  
G01 Z-.3103  
G00 X.254  
G00 Z-.2899  
G01 X.214 Z-.3099  
G01 X.164  
G01 Z-.3103  
G00 X.6  
G00 Z-.3  
(Machine Setup - 1 Turn Groove Rough )  
(TOOL #6 OD GROOVE .030 WIDE )  
G00 X.5 Z-.5982  
G00 X.35  
G01 X.3082 F3.  
G01 X.3282 Z-.5882  
G00 X.35  
G00 Z-.6149

---

G01 X.29  
G00 X.33  
G00 X.3  
G01 X.256  
G00 X.296  
G00 X.266  
G01 X.222  
G00 X.262  
G00 X.232  
G01 X.188  
G01 X.35  
G00 Z-.6349  
G01 X.29  
G00 X.33  
G00 X.3  
G01 X.256  
G00 X.296  
G00 X.266  
G01 X.222  
G00 X.262  
G00 X.232  
G01 X.188  
G01 X.208 Z-.6249  
G00 X.35  
G00 Z-.6549  
G01 X.29  
G00 X.33  
G00 X.3  
G01 X.256  
G00 X.296  
G00 X.266  
G01 X.222  
G00 X.262  
G00 X.232  
G01 X.188  
G01 X.208 Z-.6449  
G00 X.35  
G00 Z-.6749  
G01 X.29  
G00 X.33  
G00 X.3  
G01 X.256  
G00 X.296

---

G00 X.266  
G01 X.222  
G00 X.262  
G00 X.232  
G01 X.188  
G01 X.208 Z-.6649  
G00 X.35  
G00 Z-.6949  
G01 X.29  
G00 X.33  
G00 X.3  
G01 X.256  
G00 X.296  
G00 X.266  
G01 X.222  
G00 X.262  
G00 X.232  
G01 X.188  
G01 X.208 Z-.6849  
G00 X.35  
G00 Z-.7149  
G01 X.29  
G00 X.33  
G00 X.3  
G01 X.256  
G00 X.296  
G00 X.266  
G01 X.222  
G00 X.262  
G00 X.232  
G01 X.188  
G01 X.208 Z-.7049  
G00 X.35  
G00 Z-.7349  
G01 X.29  
G00 X.33  
G00 X.3  
G01 X.256  
G00 X.296  
G00 X.266  
G01 X.222  
G00 X.262  
G00 X.232



G01 X.188  
 G00 X.6  
 G00 Z-.6  
 (Machine Setup - 1 Turn Groove Finish )  
 (TOOL #6 OD GROOVE .030 WIDE )  
 G00 X.5 Z-.790  
 G00 X.33  
 G01 X.29 Z-.770 F3.  
 G01 X.168  
 G01 Z-.6103  
 G00 X.33  
 G00 Z-.5724  
 G01 X.29 Z-.5924  
 G03 X.2579 Z-.6097 I-.0172 K-.0002  
 G01 X.168 Z-.6099  
 G01 Z-.6103  
 G00 X1.0  
 G00 Z1.0  
 G49  
 G90G00G54Z0  
 G00 X0  
 M30  
 %  
 (Machine Setup - 1 Turn Groove Finish )  
 (TOOL #6 OD GROOVE .030 WIDE )  
 T6 M6 G43  
 G00 X.6  
 g00 Z.1  
 G00 x.380 z.05  
 G01 Z-.6 F4.  
 G00 X1.0  
 G00 Z1.0  
 G49  
 G90G00G54Z0  
 M30  
 %

### Program Code with Explanations:

G80 G94 G7 G40 G20 G18 G90 G54

(G80 cancels drill can cycles, G94 feed in In/Min, G7 lathe program in Diameter Mode, G40 cancels cutter comp, G20 program is in Inch, G18 program is for ZX-axis, G90 absolute mode, G54 is the base coordinate system)

T1 M6 G43 (this implements the length offsets from the tool data page for tool #1 without a move)

G00 Z.1 (this moves the distance in Z that is on the tool data page for tool #1 -.100)

G00 X0 (this moves the distance in X that is on the tool data page for tool #1)

G00 Z0

G00 Z.1 (move to clearance point in the Z-axis .100 in front of the part.)

G49 (This clears the length amounts for tool #1 without move)

G90G00G54Z0 (This moves the Z-axis by the amount in the tooling page to Z Home)

X0 (This moves the X-axis by the amount in the tooling page to X Home)

5. To run your program:

a. Click on “File” and “Open”




FIGURE 21

b. Pick your program. If your program does not show, it may have been saved as a (.NC file) instead of a (.NGC File). If this is the case, choose “All Files.”




FIGURE 22

c. Run your program.

Hit the desired icon at the top (Start, Single Step, Pause, Stop) and run your program.

**Start Button:** This button starts your program.

**Single Step Button:** This button will run your program one line at a time and stop after each move.

**Pause Button:** When you click the Pause button, it will stop the program right where it is (it will not finish the move dictated by the line of code that is running). In order to resume the program, click the Pause Button again. Your program will now resume from the point where it stopped.

**Stop Button:** When you click the Stop button, the program will stop. However, you cannot resume the program. The Stop button will reset the program to the beginning. Then you will need to click on the Start button, and the program will Restart from the beginning.

***\*NOTE:** We “Highly Suggest” that you use the “Pause” button, instead of the “Stop” button.*




FIGURE 23—The red words/abbreviations indicate their respective icons.

Thank you,  
Sherline Products Inc.

### Motor Detail

### Motor Detail

