

# SHERLINE PRODUCTS

INCORPORATED 1974

Last Retail Price Increase: OCTOBER 1, 2015

SHERLINE PRODUCTS INC. • 3235 Executive Ridge • Vista • CA 92081-8527

Tel: 1-760-727-5857 or 1-800-541-0735 • Fax: 1-760-727-7857

Email: sherline@sherline.com

www.sherline.com

Prices subject to change without notice, Updated 4/8/20

Most parts (except standard fasteners) can also be ordered online at www.Sherline.com

## Replacement Parts Price List

P/N	DESCRIPTION	PRICE	P/N	DESCRIPTION	PRICE	P/N	DESCRIPTION	PRICE	P/N	DESCRIPTION	PRICE
10840	Compound T-nut	\$2.50	20870	Collet Retaining Ring	21.00	31220	22-Tooth Gear, 24 Pitch	6.50	35030	Fixed Jaw Insert	7.75
10850	10-32 x 1/4" Skt. Hd. Cap Screw*	.65	20880	WW Collet Tailstock Adapter Body	56.75	31240	24-Tooth Gear, 24 Pitch	7.00	35040	Moveable Jaw Insert	6.00
10880	Follower Rest Brass Pads (Set of 2)	5.25	20890	8mm Collet Tailstock Adapter Body	56.75	31260	26-Tooth Gear, 24 Pitch	7.75	35050	Pull-down Bar (Pre March 1993)	4.00
10890	Follower Hold-down Tab	9.50	20970	8-32 x 1/2" Skt. Hd. Cap Screw	1.75	31270	127-Tooth Gear, 56 Pitch	19.50	35060	Convex Washer	.80
10910	Live Center Body	30.25	20980	Clock Arbor Cap	5.25	31280	28-Tooth Gear, 24 Pitch	8.25	35070	6-32 x 3/8" Flat Head Screw*	.55
10920	Live Center Point	11.50	20990	Clock Arbor Spacer	2.75	31300	30-Tooth Gear, 24 Pitch	9.00	35100	Vise Body (After March, 1993)	63.00
10930	Live Center Bearing	11.50	22100	Radius Cutter Body	94.50	31320	32-Tooth Gear, 24 Pitch	9.50	35120	Pull-down Member (After March, 1993)	9.00
10940	10-32 x 3/8" Set Screw w/ Nylon Tip	1.75	22110	Radius Cutter Support, Left	19.00	31340	34-Tooth Gear, 24 Pitch	10.00	35130	10-32 x 1-5/8" Skt. Hd. Cap Screw*	.45
11410	Set of 3-Jaw Chuck Jaws (Chuck Repair, Factory Installed Only)	78.75	22111	Radius Cutter Support, Right	19.00	31350	35-Tooth Gear, 24 Pitch	12.75	35150	Rotary Col. Attch. Fixed Clamp Disk	18.00
11420	Soft Jaws (for 3-Jaw Chks 1040/1041)	78.50	22120	Radius Cutter Pivot Pin	6.50	31360	36-Tooth Gear, 24 Pitch	10.75	35160	#2000 Col. Graduated Clamp Ring	19.75
11421	Soft Jaws (for 4-Jaw Chks 1030,1044)	89.25	22130	10-32 x 1" Button Head Socket Screw	.65	31380	38-Tooth Gear, 24 Pitch	11.25	35170	#2000 Col. Moveable Clamp Disk	24.00
11440	Set of 4-Jaw Chuck Jaws (Chuck Repair, Factory Installed Only)	89.25	22510	Quick-Change Tool Post Body	139.00	31400	40-Tooth Gear, 24 Pitch	11.75	35180	Rot. Col. Attch. Magnified Scribe Lens	6.50
11460	4-Jaw Chuck Screw	4.25	22511	Quick-Change Tool Post Riser Body	63.00	31500	50-Tooth Gear, 56 Pitch	9.75	35190	Rot. Col. Attch. Scribe Lens Mount. Blk.	3.25
11560	8.0mm WW Collet Adapter	23.25	22520	Quick-Change Tool Post L-hand Cam	4.75	31510	150-Tooth Gear, 56 Pitch	38.00	35580	Hold-down Clamp	2.75
11570	Knock-out Bar (WW Collet Set)	4.25	22530	Quick-Change Tool Post Rt-hand Cam	4.75	31560	4-40 x 7/8" Skt. Hd. Cap Screw*	.45	35620	10-32 x 7/16" Skt. Hd. Cap Screw	.65
11580	WW Collet Adapter	18.00	22550	Qk-Chg Tl. Post Carb. Insert Hldr. Bdy.	77.00	31570	Boring Head Adjustment Dial	7.00	35710	Vise Base (Rotating Vise Base)	31.50
11590	WW Collet Drawbar	31.50	22560	10-32 x 1" Cone Point Set Screw*	.45	31580	Primary Boring Head, 1.24"	50.00	35720	Rotating Base (Rotating Vise Base)	26.25
11650	WW Collet Wood Box (Deluxe Set)	15.00	22561	RH 35° Insert Holder Body	44.25	31590	Secondary Boring Head, 1.24"	34.00	35730	Clamp Ring (Rotating Vise Base)	12.75
11660	WW Collet Wood Box Insert	19.00	22570	4-40 x 1/4" Skt. Hd. Cap Screw*	.40	32010	Index Bed	68.25	35740	Vise Clamp (Rotating Vise Base)	27.00
11681	WW Collet Bolt for 2045 Index Blocks	27.75	22571	LH 35° Insert Holder Body	44.25	32020	Index Lock Pin	4.25	36010	Knurling Holder (Right)	2.25
11730	Soft Jaws (for Self-cent. 4-Jaw Chk.)	89.25	22580	T7 Torx Driver	6.50	32030	Index Spring	1.50	36020	Knurling Holder (Left)	27.00
11740	Steady Rest Brass Pads (Set of 3)	6.50	22600	Qk-Chg Tl. Post 1/4" Tool Holder Body	39.75	32040	Slow-speed Belt	17.00	36030	.030 Washer*	.70
11750	Steady Rest Body	38.00	22620	Qk-Chg Tool Post Cam Spring Pin	.95	32100	10-32 Hex Nut*	.55	36040	3/16" x 3/4" Dowel Pin	1.00
11760	Steady Rest Clamp	6.50	22630	Qk-Chg T/P Cam Springs, .120" x 7/16"	.35	32120	48 Pitch Rack	27.75	37090	3/8-16 to 3/4-16 R/T Chuck Adapter	5.75
11770	4-Jaw Chuck Jaws (Self-Centering)	89.25	22650	Qk-Chg T/P 3/8" Boring Tl. Hldr. Bdy.	48.75	32130	Indexing Case	81.00	37091	3/8-16 to 12 x 1mm R/T Chuck Adptr.	15.75
11801	3/8" Rohm Chuck	52.50	22680	Qk-Chg T/P Knurled Ht. Adjust. Knob	1.25	32140	10-32 x 1/2" Cup Point Set Screw*	.45	37092	3/8-16 to 14 x 1mm R/T Chuck Adptr.	15.75
11810	3/8" Jacobs Chuck Key	7.00	22700	Qk-Chg Tool Post Cutoff ToolHldr Body	36.00	32170	Gear Tooth Cutter Body	38.00	37093	3/8-16 to 1/2-20 R/T Chuck Adapter	15.75
11821	Bullnose Center Body	42.00	22710	Qk-Chg Tool Post Cutoff ToolHldr Clamp	8.75	32180	10-32 x 1" Thumbscrew	1.75	37094	3/8-16 to 3/8-24 R/T Drill Chuck Adptr.	15.75
11822	Bullnose Center Point	47.25	30100	Std. Headstock Assembly (w/o Motor)	107.25	32190	10-32 x 1/2" Skt. Hd. Flat Screw*	.45	37130	Worm Assembly	35.75
11823	Bullnose Center Preload Nut	6.50	30110	Hdstk Asby w/ 9/16" hole (w/o Motor)	178.25	32200	Index Case Cover	21.25	37150	Oiler Plug	2.00
11830	Milling Table Base	48.75	30111	ER-16 Headstock Asby. (w/o Motor)	173.25	32210	6-32 x 3/8" Skt. Hd. Cap Screw*	.45	37160	Preload Nut	4.00
11860	Jacobs 1/4" Chuck Key	4.50	30130	Hold-down Clamp, plain	9.50	32220	Index Gear, 72-Tooth, 48 Pitch	14.75	37170	Lock Pin	5.75
11880	#1 Morse Arbor Adapter	10.00	30133	Extended T-nut	2.00	32230	Indexing Spindle	41.75	37180	Upright	31.50
11890	#0 Morse Arbor Adapter	9.00	30134	Step Block (Anodized)	10.75	32240	Index Stepping Lever	16.25	37190	Right Angle Base	29.00
11900	Jacobs 1/4" Chuck	47.25	30135	Hold-down Clamp, stepped	10.25	32250	Index Tailstock Center	8.25	37200	10-32 x 3/8" Button Head Cap Screw	.40
11920	1/4" Carbide Tool, Right	7.50	30139	Step Block, (Not Anodized)	8.50	32260	Index Tailstock Case	22.75	37210	Hold-down Tab (requires grinding, call)	14.75
11930	1/4" Carbide Tool, Left	7.50	30140	10-24 x 1-1/4" Carriage Bolt*	.70	32500	Indexing Collar	25.25	37220	6-32 x 1/4" But. Hd. Skt. Hd. Cap Screw	.40
11940	1/4" Carbide Tool, 60°	7.50	3015	Toggle Switch Cover	9.00	32510	6-32 x 1/8" Nylon Tip Skt. Hd. Set Scr.	.95	37230	Right Angle Tailstock Case	31.50
11941	1/4" Radius Cutting Tool	7.50	30181	Rear Cutoff Tool Holder Body	44.25	32540	High-speed Belt	14.75	37240	Right Angle Tailstock Bracket	20.25
11950	High Speed Steel Tool, Right	7.50	30220	Toggle Switch Lock Ring	.55	33050	High Torque DC Motor & S/C Asby.	241.50	37510	Tilting Angle Table, Top Plate	31.50
11960	High Speed Steel Tool, Left	7.50	30230	Toggle Switch	7.75	3306	DC Motor, S/C Asby. and Headstock	336.00	37520	Tilting Angle Table, Side Plate (plain)	15.25
11970	High Speed Steel Tool, Boring	15.75	30240	No. 1 Center Drill	7.50	3307	10,000 RPM Headstock/motor asby.	420.00	37530	Tilt. Angle Table, Sd. Plate (engraved)	19.00
11980	Rocker Tool Post Body	19.00	30260	No. 2 Center Drill	7.50	3308	ER-16 Headstock/motor/S/C asby	420.00	37540	Tilting Angle Table, Bottom Plate	31.50
11990	Rocker Tool Post Center	6.50	30270	No. 3 Center Drill	7.50	33100	15" Lathe Metric-to-Inch Conversion	151.25	37550	Tilting Angle Table, Bushing	2.75
12040	Adjustable Tool Body	31.50	30360	Spur Driver Body	16.25	33120	15" Lathe M-to-I Conv., Zero Hdwls.	208.00	37560	Tilting Angle Table, Chuck Hold-down	6.50
12050	8-32 x 3/8" Skt. Hd. Cap Screw*	.50	30370	Spur Dowel Pin	5.50	33150	24" Lathe Metric-to-Inch Conversion	227.00	40010	15" Lathe Base	38.00
12060	#8 Washer	.35	30390	Wood Tool Rest Body	12.75	33200	15" Lathe Inch-to-Metric Conversion	151.25	40020	Motor Bracket	6.75
12070	9/64" Hex Key	.80	30410	Armature Support Bearing	6.75	33210	15" Lathe I-to-M conv., Zero Hdwls.	208.00	40030	Handwheel Shim Washer	.40
12080	Adjust. Live Ctr. Face w/ Brng & Point	38.00	30430	Armature Support Body	27.00	33250	24" Lathe Inch-to-Metric Conversion	227.00	40040	Drive Belt	8.75
12090	Adjustable Chuck Arbor Face	25.25	30440	3" Tool Rest (For use with P/N 1291)	26.00	33300	Std. Mill Metric-to-Inch Conversion	122.00	40050	Crossslide/Y-axis Handwheel Asby.	11.50
12100	Adjustable Tool Holder Face	25.25	30450	3" Tool Rest	25.25	33350	Deluxe Mill Metric to Inch Conversion	161.75	40060	Speed Control Bracket (For AC motors)	12.00
12120	Adjustable 1" Die Holder Face (with 13/16" Adapter Bushing)	38.00	30460	5" Tool Rest	31.50	33400	Std. Mill Inch to Metric Conversion	126.00	40070	Faceplate	10.25
12640	Compound Nut (Metric)	7.25	30480	5" Tool Rest (For use with P/N 1291)	31.50	33450	Deluxe Mill Inch to Metric Conversion	161.75	40080	Leadscrew/X-axis Handwheel Asby.	11.50
12680	Compound Slide Screw (Metric)	9.50	30490	Fly Cutter Body	38.00	33500	2000 Mill (I) to 2010 (M) Conversion	185.00	40090	Drive Dog	3.50
12720	Compound Base	34.00	30660	Slitting Saw Body	38.00	33550	2010 Mill (M) to 2000 (I) Conversion	185.00	40100	Headstock Casing	66.00
12730	Compound Rotating Base	40.25	30670	Slitting Saw Cap	9.00	34010	Oversize 2.5" Handwheel Body	19.00	40111	Tailstock Casing (Gib style)	44.25
12740	Compound Nut (Inch)	7.25	30810	1/4" End Mill	11.75	34020	Oversize Handwheel Knob	2.75	40112	Tailstock Gib	18.25
12750	Compound Clamp Ring	20.00	30820	1/8" End Mill	11.75	34030	Oversize Handwheel Shaft	2.75	40120	15" Lathe Bed	88.25
12760	Compound Slide and Tool Post	69.50	30830	3/16" End Mill	11.75	34060	Thrust Bearing Set	12.75	40160	Preload Nut	5.00
12770	Compound Gib	9.75	30840	5/16-24 x 4-1/2" Drawbolt w/ Washer	4.50	34061	Thrust Bearing Washer	1.50	40173	Plastic Backlash Adjusting Arm	5.00
12780	Compound Slide Screw (Inch)	9.50	30850	Cutoff Tool Holder	27.00	34070	Z-axis Handwheel Body (Inch)	17.75	40174	Saddle Nut (Inch)	9.00
12831	Tailstock Riser Body	45.50	30860	Cutoff Tool Blade	20.00	34080	Oversize Handwheel Plug	.95	40176	Saddle Travel Extension (2000)	12.75
12840	Tailstock Riser Clamp	12.75	30880	1/4"-20 x 5" Drawbolt with Washer	5.25	34090	Z-axis Handwheel Body, (Metric)	19.00	40177	Saddle Nut Asby. w/ Ball (Inch)	19.00
12850	Riser Rocker Tool Post Body	41.00	31010	Screw Cutting Attachment Handwheel	36.75	34110	Oversize 2.5" Handwheel Body (Metric)	19.00	40180	Tool Post Body (Standard)	13.00
12860	10-32 x 2-1/4" SHCS	.95	31020	Primary Support Arm	12.75	34210	2" Adjustable Zero Handwheel Body	19.00	40200	Leadscrew	25.25
12870	Riser 3/8" Tool Post Body	42.00	31030	Secondary Support Arm	11.75	34220	Lock Nut, Adjustable Zero Handwheel	2.75	40220	Feed Screw	9.00
12950	Headstock Riser Block	33.75	31040	Shim Washer, Small	.65	34230	Adj. Zero Hndwhl. Collar, Y/Crossld. (In.)	19.00	40230	Headstock Spindle	50.50
12980	1/4-20 x 3/8" Flat Head Screw, Slotted*	.95	31050	Shim Washer, Large	.75	34240	Adj. Zero Hndwhl. Collar, Y/Crossld. (M)	19.00	40239	Spindle w/ 9/16" hole through	75.75
12990	Headstock Pivot Pin	6.50	31060	Gear Bushing	2.00	34250	Locking Screw	2.00	40240	Lathe Pivot Pin	5.00
13910	Steady Rest Riser Body	45.50	31070	Gear Drive Pin	1.25	34260	Adj. Zero Hndwhl. Collar, Z/Ldscw. (In.)	19.00	40250	Tool Post T-nut	2.75
13920	Steady Rest Riser Clamp	12.75	31080	10-32 x 3/8" Set Screw*	.45	34270	Adj. Zero Hndwhl. Collar, Z/Ldscw. (M)	16.50	40260	Head Key	2.75
15090	Sliding Shaft (with DRO, use P/N 81509)	9.50	31090	#6 x 3/16" Pan Hd. Sht. Met. Screw*	.45	34410	2.5" Zero Handwheel Body	24.00	40270	Tailstock Spindle (Factory Installed Only)	22.75
15410	"O" Ring	.95	31100	100-Tooth Gear, 56 Pitch (with notch)	16.25	34900	Lathe Adj. Zero Hndwhl. Upgrd. Kit (In.)	105.25	40280	Thrust Collar	4.00
15420	Engagement Lever	6.75	31110	100-Tooth Gear, 56 Pitch	16.25	34901	Lathe Adj. Zero Hndwhl. Upgrd. Kit (M)	110.25	40290	1/4-20 Screw Adapter	6.50
15430	Fixed Shaft	3.50	31150	Gear Shaft	3.50	34950	Mill Adj. Zero Hndwhl. Upgrd. Kit (In.)	145.00	40300	Leadscrew Thrust	11.75
			31170	5/16 x 1-1/4" Shoulder Bolt	3.50	34951	Mill Adj. Zero Hndwhl. Upgrd. Kit (M)	145.00	40310	5-40 x 1" Skt. Hd. Cap Screw*	.70
			31200	20-Tooth Gear, 24 Pitch	6.00	35020	Moveable Vise Jaw	23.50	40320	Bearing Washer	3.00

P/N	DESCRIPTION	PRICE	P/N	DESCRIPTION	PRICE	P/N	DESCRIPTION	PRICE	P/N	DESCRIPTION	PRICE
40330	10-32 x 5/8" Skt. Hd. Cap Screw*	.45	43360	DC Motor Pulley	10.25	51170	Leadscrew, X-axis (Metric)	19.00	81300	DRO Thrust Collar, X- and Y-axis	5.25
40340	10-32 x 1" Skt. Hd. Cap Screw*	.45	43365	10,000 RPM Pulley Bracket, Outer	22.75	51171	Leadscrew, X-axis, CNC (Metric)	15.25	81350	DRO Thrust Collar, Z-axis	10.25
40370	Leadscrew Support	19.00	43366	10,000 RPM Pulley Bracket, Inner	22.75	51172	18" X-axis Leadscrew (Metric)	42.00	81500	DRO Tach. Encoder and Cable Asby.	22.75
40380	#1 Morse Center	6.50	43367	10,000 RPM Spindle Pulley	27.75	51173	18" X-axis Leadscrew, CNC (Metric)	42.00	81508	DRO Thrust Collar, Lathe Leadscrew	12.75
40390	#0 Morse Center	6.50	43368	10,000 RPM Motor Pulley	29.00	51200	Nut, Y-axis (Metric)	2.75	81509	Extended Sliding Shaft (DRO)	9.50
40400	Plug Button	.70	43460	DC Electronics	90.75	54020	Deluxe 12" Mill Base (Inch)	151.25	81510	DRO Tachometer decal	5.75
40420	Headstock Bearing	14.00	43490	DC Belt Guard Assembly	38.00	54120	Deluxe 12" Mill Base (Metric)	151.25	87510	CNC Rotary Tbl. Stepper. Motor Mnt. (Replacement only, not adaptable to std. Rotary Table)	40.50
40440	Self-tapping Screw	.40	43500	DC Motor Brushes (2, internal)	19.00	54160	5400 Y-axis Screw (Inch)	15.25	8761	CNC Computer w/driver box	1260.00
40500	10-24 x 3/4" Skt Hd. Cap Screw*	.45	43610	Chip Guard	10.25	54161	5400 Y-axis Screw, CNC (Inch)	15.25	90050	1K Potentiometer for 1/2 HP AC mtr.	21.00
40501	10-32 x 1/2" Button Hd. Hex Screw	1.25	43620	Chip Guard Hinge	5.25	54170	5400 Y-axis Screw (Metric)	15.25	90060	5K Potentiometer	9.00
40510	10-32 x 3/8" Skt. Hd. Cap Screw*	.45	44010	24" Lathe Base	88.25	54171	5400 Y-axis Screw, CNC (Metric)	15.25	90080	3/8-32 x 1/2" Hex Nut	.35
40520	10-32 x 1/2" Cup Point Set Screw*	.45	4411A	Deluxe Tailstock Assembly (Inch)	107.25	54180	Deluxe Engraved Mill Table (Inch)	80.25	90800	Model 4000 Mylar Label	.65
40530	5-40 x 3/8" Skt. Hd. Cap Screw*	.45	4411M	Deluxe Tailstock Assembly (Metric)	107.25	54182	18" Deluxe Mill Table (Inch or Met.)	194.25	90810	Model 5000 Mylar Label	.65
40540	5/16-18 x 3/4" Cone Point Set Screw*	.65	44120	24" Lathe Bed	157.25	54190	Deluxe Engraved Mill Table (Metric)	80.25			
40550	5/32" Hex Key*	.70	44171	Backlash Adjustment Body	10.50	56010	14" (8-direction) Mill Base (Inch)	162.75			
40560	3/16" Hex Key*	.70	44172	Saddle Locking Lever (Inch)	6.50	56020	14" (8-direction) Mill Base (Metric)	162.75			
40561	1/8" Hex Key*	1.50	44173	Saddle Locking Lever (Metric)	12.75	56050	Adapt. base, std. mill to 8-way col.	64.50			
40570	3/32" Hex Key*	.70	44200	24" Leadscrew (Inch)	31.50	56110	2000 Mill Column Extension Bolt	12.75			
40580	Spindle Bar ("Tommy" Bar)	.65	44210	6.5" Slide Screw (Inch)	12.75	56130	2000 Arm Hold-down Bolt	8.25			
40590	1/4" I.D. Washer*	.30	44211	6.5" Slide Screw, CNC (Inch)	12.75	56150	2000 Y-axis Leadscrew (Metric)	19.00			
40600	10-32 x 1/4" Flat Point Set Screw*	.35	44220	6.5" Slide Screw (Metric)	12.75	56151	2000 Y-axis Leadscrew CNC (Metric)	19.00			
40620	Power Cord (USA)	12.75	44221	6.5" Slide Screw, CNC (Metric)	12.75	56160	2000 Y-axis Leadscrew (Inch)	19.00			
40630	Power Cord (UK)	26.25	44230	24" Leadscrew (Metric)	31.50	56161	2000 Y-axis Leadscrew, CNC (Inch)	19.00			
40640	Power Cord (Europe)	15.75	44880	6" Crosslide (Inch)	36.75	56200	2000 Arm Hold-down Washer	13.25			
40660	3/16" I.D. Washer*	.35	4488A	Crosslide & Saddle Asby. (Inch)	152.25	56210	2000 3/8-16 x 2" Shouldered Bolt	4.50			
40670	10-32 x 1/2" SHCS*	.45	44881	Crosslide Asby., Std. Hndwhl. (In.)	56.75	56220	2000 Swing Arm (Not engraved, LH)	22.75			
40690	10-32 x 3/4" SHCS*	.45	44882	Crosslide Asby., Oversize Hndwhl. (In.)	63.00	56230	Flange Nut	6.00			
40700	10-32 x 1-3/4" SHCS*	.90	44883	Crosslide Asby., Adjust. Hndwhl. (In.)	82.00	56240	1/4-20 x 1-1/2" Skt. Hd. Cap Screw*	.50			
40710	10-32 x 1-1/4" SHCS*	.90	45010	Column (Z-axis) Leadscrew (In.) (11")	15.25	56330	2000 Swing Arm (Engraved, RH)	27.25			
40720	10-32 x 1-1/2" SHCS*	.90	45011	2000 Column (Z-axis) Leadscrew (In.)	19.00	56350	2000 Column Adjustment Block	4.75			
40730	10-32 x 2" SHCS*	.90	45012	#6 flat washer	.35	56400	2000 Arm Spacer Block	7.75			
40740	10-32 x 7/8" SHCS*	.45	45013	5-40 x 3/8" Flat head socket screw	.55	56440	2000 Arm Mount (Knuckle)	65.75			
40750	Thumbscrew 10-32 x 1/2"	1.50	45014	5-40 x 3/8" Button hd. cap screw	.80	56450	2000 Index Tab (90° bend at tip)	2.25			
40760	Thumbscrew, 10-32 x 5/8"	1.50	45030	Column Bed (Standard 11")	69.50	56470	2000 Arm Bolt Dwl. Pin (3/32" x 1/2")	.50			
40770	10-32 x 5/16" SHCS (for 3047)	.40	45040	Column Saddle	38.00	56550	2000 Column Top	33.00			
40780	10-32 x 1-1/8" SHCS*	.95	45050	Column Base (1-Hole)	67.25	56670	Adapter Base, Lathe to 8-way Column	70.75			
40820	Gib Lock	1.00	45070	Lock (Teflon®)	.65	56700	#2000 Mill Column Base	34.25			
40860	Tailstock Locking Screw Lock Grommet	1.50	45090	#4 x 1/4" Sheet Metal Screw*	.45	56700	#2000 Mill Column Extension	25.25			
40870	Tailstock Spindle Locking Screw	1.44	45100	Power Feed Bracket	6.50	61020	Horizontal Mill Base	132.00			
4088X	13" Crosslide Asby. (Saddle not incl.) (Note: 13" table is 1/4" thicker than 6" table, tool will be above centerline.)	113.50	45110	Power Feed Cord with Switch	14.00	61030	6.3" Alignment Bar	12.75			
40890	Slide Screw Insert	2.75	45120	Power Feed Motor Case	10.25	61040	2.8" Alignment Bar	6.50			
40900	10-32 x 3/8" Flat Head. Skt. Hd. Screw*	.45	45130	Power Feed Motor (120 V)	63.00	61050	Split Column Base (2-Hole)	75.75			
40910	Lathe Saddle	81.00	45140	Coupler	6.50	61060	Split Column Base, Top	44.25			
49850	Lathe Crosslide Backlash Upgrade Kit	26.25	45150	Cord Clamp (for Power Feed P/N 3001)	.80	61070	Split Column Base, Bottom	32.25			
40980	Crosslide Gib, Mill X- and Y-axis Gib	3.00	45160	Column Leadscrew (Metric)	15.25	61100	Rubber Feet (4)	6.50			
40990	Saddle Gib	3.00	45161	#2000 Z-axis Column Leadscrew (M)	19.00	61110	1/4-20 x 5/8" Skt. Hd. Cap Screw*	.60			
41040	Leadscrew / X-axis Handwheel (Metric)	11.50	45170	Column Saddle Positioner	2.75	61120	1/4-20 x 1" Skt. Hd. Cap Screw*	.70			
41050	Crosslide / Y-axis Handwheel (Metric)	11.50	45180	3/16" Ball	.65	61130	1/4-20 x 3" Skt. Hd. Cap Screw*	1.50			
41080	6-32 Hex Nut*	.30	45190	#10 Washer, Type B	.35	61140	1/4-20 x 3-3/4" Skt. Hd. Cap Screw*	1.75			
41090	8-32 x 1/2" Set Screw*	.35	45200	Bored Column Thrust (Z-axis)	6.50	67020	24" CNC Lathe Bed	159.00			
4111A	Tailstock Assembly (Inch)	82.00	45250	Power Feed Motor (240V)	69.50	67021	CNC Mill Column Bed	70.75			
4111M	Tailstock Assembly (Metric)	82.00	45260	Extended Column Bed (15")	94.50	67022	15" CNC Lathe Bed	90.75			
41130	Speed Control Knob	2.75	45270	15" Extended Z-axis Screw (Inch)	19.00	67024	15" CNC Leadscrew (Inch)	25.25			
41140	1/5 HP Spd. Cntrl. Electronics (115 V)	47.25	45280	15" Extended Z-axis Leadscrew (Met.)	19.00	67025	15" CNC Leadscrew (Metric)	25.25			
4114V	1/5 HP Spd. Cntrl. Electronics (220 V)	47.25	45290	15" CNC Z-axis leadscrew (Inch)	19.00	67026	24" CNC Leadscrew (Inch)	31.50			
41174	Locking Saddle Nut w/hole (Metric)	9.50	45291	15" CNC Z-axis leadscrew (Metric)	19.00	67027	24" CNC Leadscrew (Metric)	31.50			
41177	Saddle Nut Asby. w/ Ball (Metric)	19.00	45450	High-Torque DC Motor (Leeson)	166.00	67028	Std. Z-axis CNC Leadscrew (Inch)	15.25			
41180	1/2 HP Speed Control Electronics	47.25	45451	Motor brushes, pair (Leeson)	25.25	67029	Std. Z-axis CNC Leadscrew (Metric)	15.25			
41200	Leadscrew (Metric)	25.25	45460	High-Torque DC Motor (Protech)	166.00	67030	2000-series Z-axis CNC Ldscrw. (In.)	15.25			
41220	Feed Screw (Metric)	9.00	45465	Motor brushes, pair (Hill House 2013)	31.50	67031	2000-series Z-axis CNC Ldscrw. (M)	15.25			
41270	Tlstk. Spindle (Met., Fac. Install Only)	22.75	45470	High-Torque DC Motor (Hill House)	166.00	67035	CNC 6" Lathe Crosslide Tble	33.00			
41370	Leadscrew Support (Metric)	7.75	4588d	Adjust. Crosslide/Saddle Asby. (Inch)	178.50	67036	CNC 8" Lathe Crosslid. Tbl (7/8" thick)	45.50			
41460	Motor Brushes-1/4 HP (2)	25.25	4588M	Adjust. Crosslide/Saddle Asby. (Met.)	178.50	67040	CNC Lathe Bed Hold-down	12.75			
41890	Slide Screw Insert (Metric)	2.75	50010	10" Std. Mill Base	113.50	67050	CNC Standard Mill Table	69.50			
42040	Crosslide/Y-axis Handwheel Body	11.50	50050	Column Base (2-Hole)	57.75	67051	CNC Deluxe Mill Table (Inch)	80.25			
42050	Handwheel Shaft	1.50	50120	Pointer (Also Backlash Lock, pre 10/98)	.80	67052	CNC Deluxe Mill Table (Metric)	80.25			
42060	Handwheel Knob	2.25	50130	Backlash Nut, X-axis (Inch)	2.75	67102	CNC Mount (All axes)	40.50			
42070	6-32 x 3/16" Pan Head Machine Screw*	.40	50140	Backlash Nut, Y-axis (Inch)	2.75	67104	CNC Preload Nut (RH 1/4-28, In & Met)	3.00			
42080	Lead Screw/X-axis Handwheel Body	11.50	50150	Backlash Lock (After 10/98)	2.25	67105	CNC Coupling	14.00			
42140	Crosslide/Y-axis Hndwhl. Body (Metric)	11.50	50160	5000 Leadscrew, Y-axis (Inch)	12.75	67106	CNC Preload Nut (RH, Inch)	3.00			
42180	Leadscrew/X-axis Hndwhl. Body (Met.)	11.50	50170	5000 Leadscrew, Y-axis, CNC (Inch)	12.75	67107	CNC Preload Nut (LH, Inch)	3.00			
42470	Motor Brushes-1/2 HP (2)	21.00	50170	Leadscrew, X-axis (Inch)	19.00	67108	CNC Preload Nut (RH, Metric)	3.00			
43000	DC Speed Control Electronics Asby.	126.00	50171	Leadscrew, X-axis, CNC (Inch)	19.00	67109	CNC Preload Nut (LH, Metric)	3.00			
43100	DC Motor Standoff	1.75	50172	Leadscrew, 18", X-axis (Inch)	42.00	67111	8-32 x 3/4" Skt. Hd. Cap Screw*	.45			
43110	DC Speed Control Cover	21.50	50173	Leadscrew, 18", X-axis, CNC (Inch)	42.00	67115	5-40 x 7/8" Skt Hd. Cap Screw*	.45			
43120	DC Speed Control Hinge Plate	6.50	50180	Mill Table	69.50	67150	CNC 10" Std. Mill Base	114.75			
43130	DC Speed Control Cover Mounting Plate	5.25	50190	Lock, X-axis	2.75	67151	CNC Deluxe 12" Mill Base (Inch)	152.20			
43140	DC Speed Control Tab, Small	2.75	50200	Nut, Y-axis	2.75	67152	CNC Deluxe 12" Mill Base (Metric)	152.20			
43150	DC Speed Control Tab, Large	2.75	50210	8-32 x 1/4" Pan Head Screw*	.45	67120	CNC Preload Bearing	11.50			
43160	Belt Guard, Outer	12.75	50220	1/4-20 x 1-3/4" Skt. Hd. Cap Screw*	.65	67153	CNC 8-direction 14" Mill Base (Inch)	165.25			
43170	6-32 x 1-3/8" Pan Head Screw*	.40	50240	Pivot Pin, Mill Column	3.00	67154	CNC 8-direction 14" Mill Base (Met.)	165.25			
43180	Belt Guard, Inner	12.75	50280	Thrust Collar (Mill)	4.00	67210	CNC 8" Crosslide Leadscrew (Inch)	19.00			
43190	#2 x 1/4" Flt. Hd. Sht. Metal Screw*	.40	50910	Mill Saddle	75.75	67221	CNC 8" Crosslide Leadscrew (Met.)	19.00			
43200	DC Speed Control Mylar Label	1.75	50980	Gib, X-axis (Same as P/N 40980)	3.00	76130	6-32 x 7/16" Button Head Screw	1.50			
43230	DC Stepped Spindle Pulley	20.25	50990	Gib Y-axis (Same as P/N 40980)	3.00	76140	5/64" Hex Key	.70			
43240	6-32 x 1/4" Pan Head Screw*	.40	51130	Backlash Nut, X-axis (Metric)	2.75	81050	DRO 115VAC Pwr. Supply/Transfrm.	43.25			
43250	Insulated 16-14 Terminal	.80	51140	Backlash Nut, Y-axis (Metric)	2.75	81110	DRO Encoder Housing Cap	2.00			
			51160	5000 Leadscrew, Y-axis (Metric)	12.75	81150	DRO Stand	7.75			
			51161	5000 Leadscrew, Y-axis CNC (Metric)	12.75	81280	#2 x 3/8" Self-tap. Pan Head Screw*	.45			

For other accessories see:

- Chucks and Collets Price List
- Lathe Accessories Price List
- Mill Accessories Price List (Includes Videos and Books)
- Cutting Tools Price List

[CLICK HERE](#) for links to all current Sherline price lists.

**NOTES:**

The parts listed here are individual replacement parts, not complete assemblies. For complete assemblies or accessories, see our Lathe and Mill Accessory Price Lists. It is more expensive to purchase all the individual components of an accessory than to purchase the assembled accessory. For reference, exploded views with part numbers for all lathe and mill parts are printed in the Assembly and Instruction Guide that came with your lathe or mill. Links to the various machine exploded views can also be found on Sherline's website at Exploded Views.